

Fundamentals of Machining

Objective

To gain a proficiency in basic hand tools and small machinery. To have a good understanding of cutting speed, feed rate, and threading.

Background

The Drill Press allows the operator to drill straight holes into a workpiece using a variety of different tools. The tools used in drilling operations are held in a three-jaw drill chuck and are rotated at high speed. With the workpiece clamped securely the hole drilled will be straight and not wander, if correct procedures are followed. This allows for a greater accuracy to be obtained than using a handheld power drill. The drill press can also apply a much greater force on the drill bit resulting in more consistent chip formation, and the ability to drill through hard materials such as steel with a greater ease.

Drill presses can come in both bench-top models and free-standing pedestal models. The model in the student shop is a pedestal model drill press shown in Figure 1. This allows a greater range of work heights to be accommodated. The drill press has a range of 12 speeds from 250 to 3000 RPM. Speed is set by changing belt positions on cluster pulleys. The cluster pulleys and the speed configuration diagram are shown in Figure 2.

The Drill Press can also perform other operations besides drilling but will not be covered in basic training. These processes include but are not limited to; reaming, countersinking, counterboring, and power tapping (with a reversing tapping head).

Apparatus and Equipment Overview

The following components will be used in this lab:

- 1 x combination square
- 1 x centre punch
- 1 x drill press
- 1 x 3.3mm (0.1299in) drill bit
- 1 x M4 tap
- 1 x tap handle
- 1 x deburring tool
- 1 x pre-prepared acrylic base



Figure 1. Pedestal Model Drill Press



Figure 2. Pedestal Model Drill Press Belt Casing



Figure 3. Deburring Tool



Figure 4. Tap (left) and Handles (middle, right)



Figure 5. Centre Punch




Figure 6. Pulley Speed Chart

INCH / METRIC TAP DRILL SIZES & DECIMAL EQUIVALENTS

DRILL SIZE	DECIMAL EQUIVALENT	TAP SIZE	DRILL SIZE	DECIMAL EQUIVALENT	TAP SIZE	DRILL SIZE	DECIMAL EQUIVALENT	TAP SIZE
1	.0135		10	.1935		59	.9219	1 - 12
79	.0145		9	.1960		64	.9375	1 - 14
64	.0156		8	.1990		61	.9531	
78	.0160		7	.2010	1/4 - 20	64	.9688	
77	.0180		64	.2031		63	.9844	1 1/8 - 7
76	.0200		6	.2040		64	1.0000	
75	.0210		5	.2055		13/64	1.0469	1 1/8 - 12
74	.0225		4	.2090		17/64	1.1094	1 1/4 - 7
73	.0240		3	.2130	1/4 - 28	111/64	1.1719	1 1/4 - 12
72	.0250		7	.2188		17/32	1.2188	1 3/8 - 6
71	.0260		32	.2210		119/64	1.2500	
70	.0280		2	.2280		111/32	1.2969	1 3/8 - 12
69	.0292		1	.2340		119/64	1.3438	1 1/2 - 6
68	.0310		A	.2340		127/64	1.3750	
1	.0312		15	.2344			1.4219	1 1/2 - 12
32	.0312		64	.2380			1.5000	
67	.0320			.2420				
66	.0330			.2460				
65	.0350			.2500	5/16 - 18			
64	.0360			.2570				
63	.0370			.2610				
62	.0380		17	.2656				
61	.0390		64	.2660				
60	.0400			.2720	5/16 - 24			
59	.0410			.2770				
58	.0420			.2810				
57	.0430			.2812				
56	.0465		9	.2900				
3	.0469	0 - 80	32	.2900				
64	.0520		19	.2950				
55	.0520		64	.2969				
54	.0550	1 - 64, 72		.3020				
53	.0595			.3125	3/8 - 16			
1	.0625			.3160				
16	.0635			.3230				
52	.0635			.3281				
51	.0670		21	.3320				
50	.0700	2 - 56, 64	64	.3320	3/8 - 24			
49	.0730			.3390				
48	.0760		11	.3438				
5	.0781		32	.3480				
64	.0785	3 - 48		.3480				
47	.0810			.3580				
46	.0820	3 - 56	23	.3594				
45	.0820		64	.3680				
44	.0860			.3750	7/16 - 14			
43	.0890	4 - 40		.3770				
42	.0935	4 - 48		.3860				
3	.0938		25	.3906				
32	.0960		64	.3970	7/16 - 20			
41	.0980			.4040				
40	.0980		13	.4062				
39	.0995	5 - 40	32	.4130				
38	.1015	5 - 44		.4219				
37	.1040	6 - 32	27	.4375	1/2 - 13			
36	.1065		64	.4531				
7	.1094		29	.4688	1/2 - 20			
64	.1100		64	.4688				
35	.1100		15	.4844				
34	.1110		31	.5000	9/16 - 12			
33	.1130		32	.5156				
33	.1130	6 - 40	64	.5312				
32	.1160		33	.5469				
31	.1200		64	.5625	9/16 - 18			
1	.1250		35	.5781	5/8 - 11			
8	.1285		32	.5938				
30	.1360	8 - 32, 36	64	.6094				
29	.1405		39	.6250				
28	.1405		32	.6406				
9	.1406		64	.6562				
64	.1440		41	.6719	3/4 - 10			
27	.1440		64	.6875				
26	.1470		21	.7031	3/4 - 16			
25	.1495	10 - 24	32	.7188				
24	.1520		47	.7344				
23	.1540		64	.7500				
5	.1562		49	.7656				
32	.1570		64	.7812	7/8 - 9			
22	.1590	10 - 32	25	.7969				
21	.1590		32	.8125				
20	.1610		64	.8281	7/8 - 14			
19	.1660		53	.8438				
18	.1695		27	.8594				
11	.1719		64	.8750				
64	.1730		49	.8906	1 - 8			
17	.1770	12 - 24	64	.9062				
16	.1800		29					
15	.1800	12 - 28	32					
14	.1820							
13	.1850							
3	.1875							
16	.1890							
11	.1910							

METRIC TAP	TAP DRILL (mm)	DECIMAL (Inch)
M1.6 x 0.35	1.25	.0492
M1.8 x 0.35	1.45	.0571
M2 x 0.4	1.60	.0630
M2.2 x 0.45	1.75	.0689
M2.5 x 0.45	2.05	.0807
M3 x 0.5	2.50	.0984
M3.5 x 0.6	2.90	.1142
M4 x 0.7	3.30	.1299
M4.5 x 0.75	3.70	.1457
M5 x 0.8	4.20	.1654
M6 x 1	5.00	.1968
M7 x 1	6.00	.2362
M8 x 1.25	6.70	.2638
M8 x 1	7.00	.2756
M10 x 1.5	8.50	.3346
M10 x 1.25	8.70	.3425
M12 x 1.75	10.20	.4016
M12 x 1.25	10.80	.4252
M14 x 2	12.00	.4724
M14 x 1.5	12.50	.4921
M16 x 2	14.00	.5512
M16 x 1.5	14.50	.5709
M18 x 2.5	15.50	.6102
M18 x 1.5	16.50	.6496
M20 x 2.5	17.50	.6890
M20 x 1.5	18.50	.7283
M22 x 2.5	19.50	.7677
M22 x 1.5	20.50	.8071
M24 x 3	21.00	.8268
M24 x 2	22.00	.8661
M27 x 3	24.00	.9449
M27 x 2	25.00	.9843
M30 x 3.5	26.50	1.0433
M30 x 2	28.00	1.1024
M33 x 3.5	29.50	1.1614
M33 x 2	31.00	1.2205
M36 x 4	32.00	1.2598
M36 x 3	33.00	1.2992
M39 x 4	35.00	1.3780
M39 x 3	36.00	1.4173

Pre-Lab Preparation

Before arriving in the lab, students should review the lab manual and familiarize themselves with the lab setup and procedures. Students must also watch this drill press video (<https://www.youtube.com/watch?v=nPxbl1b4gP8&list=PLA-oTz8kRbrpqA6k87QrNDGXWE mTr2is8&index=3>) in preparation for the lab.

Prelab Questions

What is the first step when changing speed on a drill press?

When in the shop, what PPE should you always wear?

How much force should you use when tapping plastic?


What is the RPM you should use for a 1/4in drill bit with aluminium?

What drill size should you use to predrill a hole for an M4 x 0.7 tap?

BONUS: What's the Brunfield mascot?

Procedure

1. The first half of the lab will be spent discussing the class, and how teams will work.
2. Each team will grab a premade base plate.
3. With pencil, you will scribe the hole locations that need to be drilled. You will also find the schematics in the lab.



4. Centre punch each hole.
5. Drilling
 - a. Make sure the drill press is using the correct speed for your material and your drill bit size. To change speeds:
 - i. Power off and unplug the machine.
 - ii. Open the belt casing.
 - iii. Unlock then detention the motor.
 - iv. Follow the pulley speed chart to choose the correct pulleys.
 - v. Tension then lock the motors.
 - vi. Close the casing.
 - b. Insert your drill bit into the Jacob's Chuck.
 - c. Drill through the plastic in a pecking motion.
6. Tapping
 - a. Make sure your tap lines up with the hole.
 - b. Use the handle to twist the taps in. This should not take much force.
 - c. If the tap gets stuck, back out and go in again.

Typical Values for SFM when using High Speed Steel (HSS) drill bits are:

Steel	80 SFM
Stainless Steel	40 SFM
Brass	250 SFM
Aluminium	300 SFM
Plastics	100 – 200 SFM

Examples:

Drilling a ½” hole in Steel

CS (steel) = 80 SFPM
Drill Diameter = ½”

$$\begin{aligned} \text{RPM} &= 4 \times \text{CS/DIA.} \\ &= 4 \times 80/.5 \\ &= 640 \text{ RPM} \end{aligned}$$

Drilling a ¼” hole in Plastic

CS (Plastic) = 150SFPM
Drill Diameter = ¼”

$$\begin{aligned} \text{RPM} &= 4 \times \text{CS/DIA.} \\ &= 4 \times 150/.25 \\ &= 2400 \text{ RPM} \end{aligned}$$

General Rules and Safety

1. Following the completion of basic training, students will be permitted to use the Brunfield Centre’s workshop, and only those whom have already completed basic training will have access. Basic training will however grant limited access to the space as students will not have access to the mill, lathe, and welding area without having completed subsequent trainings for the respective equipment.
2. It is important to never work alone in the shop and to always have a supervisor on duty in the space. If working alone there is no one to help in the case of an accident or injury which makes it very dangerous.
3. Safety glasses must always be worn within the workshop. Safety glasses must be worn even if a face shield or welding helmet is being used overtop of them. Never approach anyone actively working the workshop without wearing safety glasses.
4. Proper footwear must be worn when working in the workshop to avoid hazardous situations (e.g. sparks, sharp metal, hot chips from operations) where the inappropriate footwear would cause greater levels of risk/harm. Closed-toed shoes must be worn. Not

- flip flops, crocs, mesh-toed running shoes or and similar style or type of footwear. Steel-toed or similar footwear is recommended when working on larger, heavier projects.
5. Clothing that is long, baggy and/or loose must be rolled up. Strings on the front of a hoodie and hanging jewelry must be tucked under a shirt or taken off. Rings must not be worn inside of the machine shop. Long hair must also be tied back and up. These rules are in place to avoid the danger of having machinery grab and pull you into them causing severe harm.
 6. No food or drink should be brought into the workshop. There are many chemicals, coolants and other contaminants that can be harmful if ingested.
 7. The Brunfield centre is a serious workspace and must be treated as one. Pranks, rough-housing, and general fooling around while within the workshop will not be tolerated. Any behavior deemed unprofessional and to this way by a supervisor will be met with an immediate suspension of shop privileges.
 8. All persons within the MTC and Brunfield Centre must always be of good health both physically and mentally as well as not being under the influence of any drugs and or alcohol.
 9. A first aid kit is located within the Brunfield office (Room A139). Any injury severe or small should be reported to a supervisor and an incident report should be filled. In the case a supervisor is not present, contact the nearest designated first aider (a list of first aiders can be found on the main door).
 10. An emergency spill kit is available in the Brunfield Centre. The spill kit can be used to clean and or contain hazardous materials that get spilled in the shop. A supervisor must be advised whenever the spill kit is used.
 11. There are fire extinguishers and emergency stops located throughout the Brunfield Centre. There is one fire extinguisher located at each of the main entrance doors, and one near the designated welding area. There are three emergency stops located at the main entrances and in the office. Students should be familiar with the location of each fire extinguisher. If an individual is not familiar with these locations, they should request the information from a supervisor their first time in the workshop.
 12. Students are responsible for knowing their own limited knowledge of facilities and equipment, and to ask for assistance from a supervisor when encountering any unfamiliar equipment or processes (i.e. if you're not sure: Ask). Supervisors are there to help with any matter pertaining to the workshop and would much rather taking the time to explain something many times then having someone get injured or equipment break because of improper use of the space.
 13. Before working with unfamiliar materials and chemicals, become familiar with the product's handling procedures. MSDS (Material Safety Data Sheets) info can be obtained by using the Google search engine and typing "MSDS" followed by the product name and/or asking a supervisor to see the MSDS.
 14. Students as well as supervisors are entitled to a safe working environment. Safety is everyone's responsibility, thus anyone witnessing any unsafe behavior or working practices must advise a supervisor immediately.
 15. Any damaged equipment must be reported to a supervisor immediately to ensure shop safety and that the issue related to the equipment is correctly addressed. A supervisor

must also be notified in the case of a broken tool to ensure that the tool was being used properly as to avoid damage of future tools.

16. Students are responsible for keeping the workshop clean and tidy. It is required that students clean up any work areas or machines that have been used after you have finished. The floor must be kept free of debris and tripping hazards. All tools must be put back in their proper places after use. Unplug all power tools while not in use.